

Live FireRECORDS

Incident Report

Incident Number: 1887368	Number of Alarms: 1	Date: 11/23/2018	Time: 19:06
Shift: B	District: 1131A	Exposure: 000	Station: 06
Alarm Time: 11/23/2018 19:06	Arrival Time: 11/23/2018 19:22	Controlled Time: 11/24/2018 03:16	Cleared Time: 11/24/2018 07:48

Incident Address

Dispatch Address: 13802 ROCKRIDGE RD	Actual Address: 13802 ROCKRIDGE RD	Address Type: 1 - Street address
Property Use: 419 - Single Family Dwelling	Insurance Carrier:	Common Name:
Latitude:	Longitude:	Phone:

Incident Classification

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Incident Type as Dispatched:	1 - Fire
Actual Incident Type:	111 - Building fire
Mutual Aid:	1 - Mutual aid received
	FDID: 05102
	State: FL
	Incident Number: 1887368
Hazardous Materials Release:	N - None

Actions Taken:

11 - Extinguishment by fire service personnel	76 - Provide water
12 - Salvage & overhaul	81 - Incident command
14 - Contain fire (wildland)	82 - Notify other agencies.
21 - Search	86 - Investigate
24 - Recover body	

Value - Property: 150000	Contents: 50000	Loss - Property: 150000	Contents: 50000
---------------------------------	------------------------	--------------------------------	------------------------

Authorities

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike


Member Making Report: 11286	Officer In Charge: 0838
Other Authorities:	Report Completed: Yes

Member Name:	Role:
---------------------	--------------

Incident Persons Involved

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Person Involved:



Incident Property

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Area Of Origin: UU - Undetermined

Heat Source: UU - Undetermined

Item First Ignited: UU - Undetermined

Material First Ignited: UU - Undetermined


Cause of Ignition: 2 - Unintentional

Buildings:

Residential Units: 1

Acres Burned: 1.0

On Site Materials:



Incident Structure

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Structure Type: 1 - Enclosed building

Status: 2 - In normal use

Item Contributing to Flame Spread: 17 -
Structural member or framing

Material Contributing to Flame Spread: 63 -
Sawn wood, including all finished lumber

Fire Spread: 4 - Confined to building of origin

Main Floor -

Length: 0

Width: 0

Area: 3000

Story of Origin: 1

Floors Below Grade:

Floors Above Grade: 1

Floors Damaged -

Minor:

Significant:

Heavy:

Extreme: 1

Total:

Incident Personnel

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Personnel ID	Last Name	First Name	Rank / Position
26593	Gonzalez	Manuel	FF
11286	Williams	James	CAPT
22403	McMorrow	Kelly	FF
26653	Moersch	Nicholas	FF
0838	Gilley	Jeremiah	BC
4710	Gorokhov	Yevgeniy	BC
18418	Quinn	Courtney	CAPT
5042	Culpepper	Kevin	EN
4851	Forbes	Alfred	FF
5019	Parnell	Garrett	CAPT
13421	Sheehan	Britney	EN

18729	Harris	Lee	FF
1204	Jones	Joe	EN
3921	Sherouse	Keith	CAPT
20852	Musick	Justin	FF
26596	Green	Timothy	FF
4949	Abnathy	Thomas	FF
26422	Perez	Andrew	FF
26999	Bentz	Eric	PM
26883	Delucia	Devin	FF
2324	Vittone	Raf	DC
26424	Walker	Desmond	FF

Personnel Actions Taken

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Action
1 - Fire Control or Extinguishment
11 - Extinguishment by fire service personnel
12 - Salvage & overhaul
21 - Search
24 - Recover body
31 - Provide first aid & check for injuries
55 - Establish safe area
73 - Provide manpower
74 - Provide apparatus
76 - Provide water
81 - Incident command
82 - Notify other agencies.
84 - Refer to proper authority
86 - Investigate

Incident Apparatus and Resources

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Unit ID	Dispatched	En-route	Arrival	Cleared Scene	Arrive Facility	Cleared Facility	In Service	In Qtrs
EN006	11/23 19:08	11/23 19:10	11/23 19:22			11/24 05:14		11/24 05:14
BC003	11/23 19:08	11/23 19:10	11/23 19:29			11/24 04:46		11/24 04:46
MR006	11/23 19:08	11/23 19:08	11/23 19:27			11/24 04:26		11/24 04:26
BC001	11/23 19:08	11/23 19:10	11/23 19:29			11/24 04:47		11/24 04:47
SQ007	11/23 19:08	11/23 19:08	11/23 19:30			11/24 04:24		11/24 04:24
EN039	11/23 19:08	11/23 19:09	11/23 19:35			11/24 04:40		11/24 04:40
EN023	11/23 19:15	11/23 19:16	11/23 19:26			11/24 04:45		11/24 04:45
TE039	11/23 19:13	11/23 19:13	11/23 19:37			11/24 04:40		11/24 04:40

TE004	11/23 19:53	11/23 19:54	11/23 20:45			11/24 07:48		11/24 07:48
BR023	11/23 19:55	11/23 19:55	11/23 19:55			11/24 05:17		11/24 05:17
AT019	11/23 19:38	11/23 19:45	11/23 20:48			11/24 04:29		11/24 04:29
MD231	11/23 19:36	11/23 19:36	11/23 19:55			11/24 04:15		11/24 04:15
FC506	11/23 21:18	11/23 21:18	11/23 22:17			11/23 23:50		11/23 23:50
TE015	11/23 19:53	11/23 19:53	11/23 20:30			11/23 22:59		11/23 22:59
TE006	11/23 19:24					11/23 19:34		11/23 19:34

Apparatus Actions Taken

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Action
11 - Extinguishment by fire service personnel
12 - Salvage & overhaul
14 - Contain fire (wildland)
21 - Search
24 - Recover body
31 - Provide first aid & check for injuries
73 - Provide manpower
74 - Provide apparatus
76 - Provide water
81 - Incident command
82 - Notify other agencies.
84 - Refer to proper authority
86 - Investigate
93 - Cancelled

Incident Civilian Casualty

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Title: Engine-6 Narrative Text:	Type: 1 - Incident	Author: James Williams
<p>EN06 arrived on scene of a structure that was located approximately 300ft off the main access road. EN06 was not able to get close to the structure due to the driveway being covered with trees and a sign. Visibility of the structure upon arrival was not obtainable because trees covered the property, and tightly surrounded the home. First observation while attempting to complete a 360 of the incident was a medium size structure that appeared to have heavy fire involvement on the bravo-charlie side that involved the interior and extended through the roof which signaled potential fire throughout the attic as smoke was exiting all four corners of the home. Yard debris, lighting and vegetation hindered us from getting completely around the home. Command was established and a power drop was requested . Command then gave the order to establish a court yard lay that would supply water back to the structure so we could attempt a primary search for the occupant. The fire conditions at this time were severe and the power lines that were at the alpha-delta corner fell. This hindered our attempt to access the delta side of the home due to the lines being energized. Command then requested confirmation from dispatch that the information received was from someone inside the home since conditions to enter were not possible without water and deteriorating quickly hindering, any ability for firefighters to make entry. Prior to EN23 arrival on scene they were given direction that their assignment was to establish a water supply and to provide crew members for a primary search of a possible victim. Command determined that the fire was rapidly spreading through the home and a search could not be performed. The home quickly became 100% involved which changed the tactics to defensive since a rescue was no longer achievable. Battalion Chief-1 arrived and was given a conditions, actions and needs report. Battalion Chief-1 took over command at this time.</p>		
Title: BC003 Narrative Text:	Type: 2 - Company	Author: Yevgeniy Gorokhov

Battalion 3 (BAT3) arrived on a fire scene; initial command had been established by Engine 6 (EN6); during the follow up report EN6 advised that accountability was placed by EN6, BAT3 assumed the accountability role at the same time Battalion 1 (BAT1) assumed Command from EN6; all fire ground personnel were staged at the accountability area and deployed for assignments from the same area; Medic 231 (MD231) was assigned to set up rehab 20-30 feet away from the front bumper of EN6; vital signs were obtained on every firefighter that came in for recycle or rehab; Shift Duty Officer was notified, food and more water supplies were delivered on scene due to an extensive overhaul; everybody was accounted for at all times; no injuries were reported to Command or Accountability.

Title: Engine 23
Narrative Text:

Type: 2 - Company

Author: Keith Sherouse

EN23 arrived on scene with direction from command to establish a water source and provide manpower at the alpha side of the structure.

Captain-23 attempted to make a complete 360 of the structure to assist command with determining if there was the ability to gain access into the structure for from another point for a rescue attempt. The home was too heavily involved, upon EN23 arrival for any possibility of making entry. Command determined that the fire needed to redirect into a defensive mode. Battalion Chief -1 arrived on scene and took over command.

Engineer 23 was assigned water supply officer. No hydrant was located in the area and dump tank/Tender operations was utilized. Hydrant was established at Cypress Lakes sub division. Approximately 28,000 gallons of water was used to extinguish fire. Additional water was needed and Auburndale Fire was called for a mutual aid tender (T-421). Tender 421 supplied 9000 gallons of the water used.

Captain 23 was reassigned to Alpha Operations and defensive strategy continued while recycling crews through Accountability Officer until fire was extinguished and overhauled. All crew members cleared from scene by Command.

Engine 23 and Brush 23 returned to station out of service until units was refueled and refilled with water.

Title: Squad 7/ Brush 23	Type: 2 - Company	Author: Garrett Parnell
Narrative Text:		
<p>Squad 7 was dispatched to a report of a residential structure fire at the above location. SQ 7 was designated as the third arriving engine and was directed to supply EN 23 with water upon arriving on scene.</p>		
<p>SQ 7 arrived on scene and made access to EN 23 down a long dirt driveway. SQ 7 crew supplied EN 23 with a section of 2 1/2" supply line. Command (Battalion1) ordered SQ 7 crew to back our unit out to the hard road and return to the scene on foot for further instruction.</p>		
<p>Upon returning to the staging area, Command directed SQ 7 crew members to man Brush 23. BR 23 was sent to the East of the fire scene to check for exposures and control the brush fire started by the structure fire. Captain 7 was designated as "Charlie Division". Access was made to the assigned area and no structural exposures were found. Crews were not able to access the brush fire due to large trees and multiple fences. BR 23 returned to the staging area and "Charlie Division" was disbanded.</p>		
<p>BR 23 was directed to return to the Alpha side of the structure and extend a line to extinguish spot fires on the charlie and bravo sides under the direction of "Alpha Division". After extinguishing the spot fires, crew members assisted with overhaul operations of the main fire structure. Crew members continued in this role until SQ 7 was cleared by Command.</p>		
Title: E39	Type: 2 - Company	Author: Courtney Quinn
Narrative Text:		

Upon arrival E39 found structure fully involved.E39 pulled pre connect off of E23 and connected to courtyard lay for fire suppression.E39 provided man power for fire control and salvage and overhaul.

Title: T39

Type: 2 - Company

Author: Courtney Quinn

Narrative Text:

T39 provided dump tank and water for fire operations.

Title: Battalion 1 (Incident Command)

Type: 1 - Incident

Author: Jeremiah Gilley

Narrative Text:

Battalion 1 arrived on scene to find a working residential house fire. Battalion 1 had called for a power drop while en route to the scene. Captain 6 repeated the request to Dispatch again after he arrived on scene and identified a working structure fire. The home was located on an unpaved road in the woods and was heavily surrounded by pine trees. The working structure fire could not be seen from Rock Ridge Road. Initial responding crews had extreme difficulty locating the residence because of the secluded location, the lack of an address on Rock Ridge Road that could be seen visually, and the distance of the structure from the roadway. E-6, E-23, Battalion 3, and Rescue 6 were already on scene prior to my arrival. Command had been established, a courtyard lay fire attack line was deployed down the driveway to the structure, and crews were working to establish a water supply. Captain 6, as Command, had declared a defensive attack mode. The area does not have hydrants. The closest commercial hydrant is approximately 5 to 6 miles away. A water nursing operation was utilized between apparatus until a dump tank operation could be set up and utilized. Crew members were attempting to fight the fire defensively from the Alpha side (front) of the structure. Battalion 1 met up face to face with Battalion 3 and assigned him the function of Accountability of on scene personnel. Battalion 1 also met up with Command, (Captain 6) and assumed Command from him after receiving a face to face C.A.N. report. A P.A.R. was performed. Captains and Firefighters, 4 personnel total initially, were located on the Alpha

side and were designated Alpha Division for tactical operations. Alpha Division used a one and three quarter inch attack line, derived from the two and a half inch courtyard hose lay, for initial fire attack and for protection. Captain 23 performed a 360 walkaround of the structure to ensure a rescue attempt was not feasible. An energized power line was down on the Delta side (right side) of the structure. Captain 23 reported very high heat conditions all around the structure and visual flames in every doorway and window of the house. Squad 7 arrived on scene shortly behind Battalion 1 and assisted with manpower and checking the area for other structures that may be exposed. They also performed recon. of the wooded area around the home because a brush fire had begun in many locations around the home.

Tenders 39, 4, and 15 also arrived with AFD Tender 421 to facilitate tender shuttle operations. Once an adequate water supply was established a second one and three quarter inch handline was put into use from the same two and a half inch courtyard lay. Alpha Division defensively attacked the fire from the Alpha side of the structure. The State Fire Marshal's Office was notified and briefed at this time. Once safe, and after most of the fire had been extinguished, crews began to enter the now collapsed structure and conduct a primary search. The State Fire Marshal's was again notified and asked to come enroute to the scene for fire origin and cause determination. Extensive overhaul was performed to ensure complete extinguishment of the structure. The primary search turned up one casualty inside the structure. The casualty had been the 911 caller who initially reported the fire. No further discoveries were made with secondary search. Extensive overhaul was performed throughout the night. Polk County Sheriff's Office crime scene responded to the address, along with additional resources from the State Fire Marshal's Office. Polk County Fire Rescue crews performed shift change and E-6 returned to assist with body removal and identification operations. The chimney of the home was pulled down because it had become a safety hazard. Once the PCSO and the State Fire Marshal's investigation was complete, the home was turned over to the owner of the property.

Title: Additional Information **Type:** 5 - Other **Author:** Mike Linkins
Narrative Text:

Investigation module updated to list State Fire Marshal as the investigating agency. Detective M. Taylor as the point of contact.

Equipment Used

Incident: 2018-1887368-000 Version 90 of 90 Saved On: 2/5/2019 3:18:40 PM by Linkins, Mike

Type: GAL - Estimated
water used (gallons)

Quantity: 28000

Description: 28000
gallons of water used.

Apparatus: EN006

Type: GAL - Estimated

Quantity: 750

Description:

Apparatus: EN023

water used (gallons)

Type: GAL - Estimated water used (gallons)	Quantity: 750	Description:	Apparatus: SQ007
--	----------------------	---------------------	-------------------------

Type: GAL - Estimated water used (gallons)	Quantity: 6000	Description:	Apparatus: TE004
--	-----------------------	---------------------	-------------------------

Type: GAL - Estimated water used (gallons)	Quantity: 12500	Description:	Apparatus: TE039
--	------------------------	---------------------	-------------------------

Type: GAL - Estimated water used (gallons)	Quantity: 7500	Description:	Apparatus: TE015
--	-----------------------	---------------------	-------------------------

Type: GAL - Estimated water used (gallons)	Quantity: 250	Description:	Apparatus: BR023
--	----------------------	---------------------	-------------------------
